

From: "Stefanoff, Jim/SPK" <jstefano@CH2M.com>
 To: "'voytilla.marykay@epamail.epa.gov'" <voytilla.mar...>
 Date: 11/23/98 9:10am
 Subject: Sampling Schedule

To date the following samples have been collected:

November 5: Complete 5 Level
 November 13: Complete 9 Level
 November 20: 3 Level

Thus, we have one complete round.

Proposed Future Sampling Plan:

December 1: 9 Level Loadout flume change and samples from 9LA, 9BS, 9PU, and 9KT

December 2: 5 Level Williams weir change and complete sampling (3 done at the same time as 5)

Mid-December: Complete 9 Level

Start 1st week January: Once a month all stations, schedule 5 Level when Bob Hopper is doing Cherry Raise Maint.

Continue 1/month until snow begins to melt and flows begin to pick up.

Once flows are Climbing: Every 2 weeks until the flows are back down - about through June/July.

August: Scheduled end point.

- Flows + samples one full round
all flumes in place.

(what parts generate water no. metals)

- Bob's people take some measurements maybe? We could approach him.

114247

USEPA SF



1076348